

ADDITIONAL MAINTENANCE PROCEDURE FOR THE MODEL MBK13-090BSX-P1L

This additional procedure is used in case that during the service of the model MBK13-090BSX-P1L with NF certificate number EA9 392 863 A0, add the agent (BSX233, 135ml), at a flacon flottant, instead of a premix.

The service maintenance must be exactly the same like the document named 'PROCÉDURE GÉNÉRALE DE MAINTENANCE POUR LES EXTINCTEURS DE LA SA MOBIAK À pression auxiliaire (Poudre-Mousse-Eau plus Additif) with issue date: June 2015 and revision date 04/11/2022 Edition: 6' referring but adding the below steps before ending the procedure.

- Replace the current label of the fire extinguisher with the new one that must be supplied from MOBIAK SA with specific specifications. This new label must be placed either by removing the old one (in case that the fire extinguisher is using label), or by covering 100% the silk screening of the fire extinguisher.
- Replace the maintenance procedure document with the new one **'PROCÉDURE GÉNÉRALE DE MAINTENANCE POUR LES EXTINCTEURS DE LA SA MOBIAK À pression auxiliaire (Poudre-Mousse-Eau plus Additif) with issue date: June 2015 and revision date 04/11/2022 Edition: 6'**
- The responsible person that is performing the above action must fill the below table (Annex 1) for traceability reasons and he must also inform MOBIAK by sending the complete table by email.
- The maintenance company and MOBIAK, are responsible to keep these records until the fire extinguisher withdrawn.

ANNEX 1

| Product code | NF approval number | Serial number of the Cylinder | Cylinder Manufacturing year | Batch Number of the Valve | Lot number of the Assembly |
|--------------|--------------------|-------------------------------|-----------------------------|---------------------------|----------------------------|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

